
The following content was supplied by the authors as supporting material and has not been copy-edited or verified by JBJS.

Supplementary Figure 1. Manual correction for misjudged cartilage. A. Fatsuppressed spoiled gradient echo sequence image for cartilage. B. Femoral cartilage automatically selected by our software. Femoral cartilage is shown as a green area but the water-cartilage boundary is slightly misjudged. C. Manual correction. Misjudged area was selected along the water-cartilage boundary with a lasso tool. D. Cartilage area after manual correction.



Supplementary Table 1. The projected cartilage area ratio (%) (for cartilage thickness \geq 1.5 mm) used to determine the measurement error. After the first MRI, the volunteers stepped off the MRI platform for a moment, and then the knee MRI scans were repeated.

	Anteromedial		Anterolateral		Posteromedial		Posterolateral	
	1st	2nd	1st	2nd	1st	2nd	1st	2nd
	MRI	MRI	MRI	MRI	MRI	MRI	MRI	MRI
Knee 1	89	88	97	97	67	68	97	97
Knee 2	96	96	97	96	91	91	99	99
Knee 3	99	99	93	95	86	88	99	99
Knee 4	99	98	99	99	89	88	98	96
Knee 5	97	97	95	97	91	90	99	99
Knee 6	93	91	93	91	73	72	97	98
Knee 7	99	98	92	92	92	92	98	98
Knee 8	99	99	100	100	91	89	99	99
Knee 9	98	98	100	100	97	97	100	100
Knee 10	95	97	96	95	87	85	100	99

Supplementary Table 2. Absolute value of the difference for the projected cartilage area ratio (%) (for cartilage thickness ≥ 1.5 mm) between the first and the second MRI determinations.

	Anteromedial	Anterolateral	Posteromedial	Posterolateral	4 segments
Knee 1	1	0	1	0	
Knee 2	0	1	0	0	
Knee 3	0	2	2	0	
Knee 4	1	0	1	2	
Knee 5	0	2	1	0	
Knee 6	2	2	1	1	
Knee 7	1	0	0	0	
Knee 8	0	0	2	0	
Knee 9	0	0	0	0	
Knee 10	2	1	2	1	
Average	0.7	0.8	1.0	0.4	0.7
SD	0.8	0.9	0.8	0.7	0.5